

HAER
OHIO
75-LOCK.V,
1-

HISTORIC AMERICAN ENGINEERING ~~SURVEY~~
RECORD

Index To Photographs

East Lockington Road Bridge
East Lockington Road spanning the Great
Miami River 1.03 miles east of Lockington,
Shelby County, Ohio.

HAER No. OH-76

PHOTOGRAPHER: (All views) John Gerhardstein October, 1990

- OH-76-1 Overall view of east and north sides. Looking from northeast towards southwest.
- OH-76-2 Overall view of south side. Looking from southwest towards northeast.
- OH-76-3 View of first span showing typical beam, "U" bolt, lower eyebolt chord, verticals, diagonals, and top chord. Also included is part of typical pier construction. Looking from north to south.
- OH-76-4 View of fourth span showing typical top chord, diagonals, verticals, lower eyebolt chord, "U" bolt, and floor beam. Looking from south to north.
- OH-76-5 Looking thru deck from east to west.
- OH-76-6 Looking thru deck from west to east.
- OH-76-7 Typical end portal detail. Looking at connection of first and second span, south side.
- OH-76-8 Typical bolt connection for top chord, eyebolt diagonal and vertical lattice. Looking at third span, third panel, north side.
- OH-76-9 Looking down at connection of third and fourth spans, south side. This is typical for all connections.
- OH-76-10 Typical connection for floor beam, "U" bolt, eyebar lower chord, diagonals, and vertical lattice. Looking at fourth span, between third and fourth panels, south side.

Note: An aerial photograph of the East Lockington Road Metal Pony Truss Bridge is incorporated within a survey flown in 1974 is found at the Shelby County Engineer's Office, Sidney Ohio.

KEY to PHOTOGRAPHS
 East Lockington Road Bridge
 HAER No. OH-76 (Page 2)

